

58

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 58 Grid Reference 020 367 Map Sheet No 88

Name of Owner/Quarry: _____

Working Pit/Disused Pit/New Locality: Disused 10 years +

Past Production: 600m³ Estimated Reserves: V. Small.

Description of site: on sharp corner of the Glen Huon Road.
Fenced off, slightly overgrown

Limits to expansion: fence, house, road.

Thickness of overburden: 25cm white sands.

Sources of information: RAAM Field: 16/3/79 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Rounded sandy gravel and layers of bedded sands - Tertiary.

History: _____

Remarks: No material to sample.