

54

88063

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. S4* Grid Reference 396 364 Map Sheet No 88

Name of Owner/Quarry: Gelibrand Estate. - Collins Springs.

~~Working Pit/Disused Pit/New~~ Locality: Disused & y+ - Being Rehabilitated

Past Production: 3500 m³ Estimated Reserves: _____

Description of site: Three neighbouring areas of very shallow surface stripping on moderately sloping land, just to the W. of the St. Arm. Rd.

Limits to expansion: Road, new housing estate (is part of)

Thickness of overburden: 0-5cm unwanted sands.

Sources of information: RAM Field: 10/1/79 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	15.0	11.8	7.6	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038	
	75.0	53.0	37.5	26.5														
A 1										Tr.	99.9	99.8		96	22	0		
														72				
B 2										0	99.9	99.8		96	25	4	2	
										0	0	0		4	73	75	96	98

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): SP

Geological Description: Fine white sand

History: _____

Remarks: Being actively rehabilitated at present.
Average depth of sand extracted - 35cm.