

10a

88074

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 10a Grid Reference 254 385 Map Sheet No 88

Name of Owner/Quarry: \_\_\_\_\_

Working Pit/Disused Pit/New Locality: Not worked for at least 10 years.

Past Production: 1000 m<sup>3</sup> Estimated Reserves: Very small.

Description of site: Very shallow patch of bare sand on slight slope to East. Behind housing sub-divisions of Blackmans Bay.

Limits to expansion: Environmental aspects.

Thickness of overburden: 40cm of sandy overburden.

Sources of information: RAAM Field: 15/3/79 Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	15.0	11.8	7.5	4.76	2.36	1.18	0.60	.30	.212	.150	.075	.038	
1													TRACE	98	80	35	5	3
2												0	2	20	65	95	97	
3												0	2	18	45	30	2	
4																		

L.I. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): SP-SM

Geological Description: Light grey to brown shallow sands over a grey clayey hardpan.

History: \_\_\_\_\_

Remarks: Sampled.