

S12

88077

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. S 12 Grid Reference 234 382 Map Sheet No 88

Name of Owner/Quarry: _____

Working Pit/Disused Pit/New Locality: Not worked recently

Past Production: 800m³ Estimated Reserves: Small-Moderate

Description of site: Large surface disturbance to the east of Coffee Creek
Near loamy gully and in rough ferny pasture; flatish site.

Limits to expansion: None apparent (physical) visual and economic grade.

Thickness of overburden: ~5cm

Sources of information: RAAM. Field: 16/3/79 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	14.9	10.5	7.6	5.3	3.8	2.8	2.0	1.5	1.1	0.8	0.6	0.4	0.3	0.2	0.15	0.1	0.075	0.05	0.038
1																								
2																								
3																								
4																								

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): SP-SM.

Geological Description: Slightly loamy impure grey fine sand.

History: _____

Remarks: 150x50x.1

Not Sampled.

Other pits apparent on other side of coffee creek - on Hazell Bros and Bulf house - mainly loam pits.

* Pasture regrowth.