

S 18

88079

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. S 18 Grid Reference 094 122 Map Sheet No 88

Name of Owner/Quarry: _____

Working Pit/Disused Pit/New Locality: Occasionally washed (recent)

Past Production: 1000 m³ Estimated Reserves: Small

Description of site: Minor removal of impure sands at end of large pit (sampled) and in small pits close to Rendalls Bay Road.

Limits to expansion: Gravel.

Thickness of overburden: 10-30 cm.

Sources of information: RTAM Field: 9/4/79 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): SP

Geological Description: Impure fine white quartz sand.
Organic contamination.

History: Only recently extracted. - bygrnet Council.

Remarks: 2000 m² X .2m = 400m³; 3000m² X .2m = 600m³
Sampled.