

Hd 88084

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. Hd Grid Reference 095124 Map Sheet No 88

Name of Owner/Quarry:

Working Pit/Disused Pit/New Locality: Occasionally worked.

Past Production: 14,000 m³ Estimated Reserves: small.

Description of site: Extensive lignum pit and scattered shallow scrapings extending in arc 800 m behind Randsale Bay. Behind 11a.

Limits to expansion: Pit 11a, pasture land to North.

Thickness of overburden: < 20 cm.

Sources of information: RAAHM Field: 9/14/79 Laboratory: Ref. No.:

Sizing analysis: 28.8.77. Date:

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1			100	97	88	71	56	54			42			20	
2															
3															
4															

8
End

L.L. 35 P.I. 20 L.S. 9 D.R. 0.48.

Special tests:

Group Symbol (unified soil classification system): GW-GC.

Geological Description: As for 11a though higher clay. Sandy ss (S19) in patches.

History: Pits in this area 40-50 years old and originally owned by J.S. Bennett. This area mainly used by Council?

Remarks: More clay apparent in this pit, but Council use for road gravel and then seal over it.

