

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 75/5 Grid Reference EN 343929 Map Sheet No 8312

Name of Owner/Quarry: G.T. HOUSEGO - "ELDON"

~~Working Pit/Disused Pit/New~~ Locality: NOT USED FOR AT LEAST 5 YRS

Past Production: 2000 m<sup>3</sup> Estimated Reserves: Very Small.

Description of site: ROADSIDE PITS & SCRAPINGS UP  
EMBANKMENT ON ELDON RD.

Limits to expansion: NO PHYSICAL BARRIER; CLAY CONTENT TOO HIGH.

Thickness of overburden: ~25 CM RUBBLE & SOIL

Sources of information: RAMM Field: 10/10/78 Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	12.5	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1			100	98	94	86	77	71			66				54
2															
3															
4															

L.L. 33 P.I. 16 L.S. 9 D.R. 0.82

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): CL

Geological Description: FINE SILTSTONE GRAVEL, SILT & CLAY

History: USED BY RICHMOND COUNCIL IN PAST.

Remarks: \_\_\_\_\_