

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 75/9 Grid Reference ^{EN} 177853 Map Sheet No 8312

Name of Owner/Quarry: H.G. SWAN - SWANS HILL - BAGDAD

Working Pit/Disused Pit/New Locality: ON

Past Production: 38,000 m³ Estimated Reserves: MODERATE

Description of site: SITUATED ON N. SIDE OF SWANS HILL (NEAR SUMMIT)

REACHED BY STEEP ROAD FROM HIGHWAY. SURROUNDED BY PASTURE

Limits to expansion: NONE

Thickness of overburden: 30-60 cm CHOCOLATE (KRAZNOZEM) SOIL

Sources of information: RAAM Field: 6/10/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: PND Date: 1975

% PASSING

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1		100	98	77	64	53	38	24			12			8	
2	100	93	85	75	66	58	50	36			21			11	
3	100	84	71	57	48	42	31	22			10			5	
4															

L.L. 50/37/39/ P.I. 33/21/24 L.S. 12/10/9 D.R. 63/54/43

Special tests: _____

Group Symbol (unified soil classification system): GP-GC

Geological Description: PARTLY DECOMPOSED DOLERITE.

History: D.M.R. MAIN USER ON MIDLANDS HIGHWAY IN PAST
SOME GREEN PONDS COUNCIL USE.

Remarks: PIT IRREGULAR SHAPE. IN PART WORKED AROUND
A LARGE "PLUG" (?) OF DOLERITE.