

TASMANIAN CONSTRUCTION MATERIALS REGISTER

EN

Serial No. 75/23 Grid Reference 268748 Map Sheet No. 8312

Name of Owner/Quarry: J. WEBBERLY - MERRIWORTH ROAD

Working Pit/Disused Pit/New Locality: NOT USED FOR 6+ YEARS.

Past Production: 12,500 m³ Estimated Reserves: MODERATE

Description of site: PIT SET INTO SIDE OF HILLOCK JUST TO THE NORTH WEST OF ACCESS ROAD TO OWNERS HOUSE.

Limits to expansion: NONE

Thickness of overburden: 30-60 cm POOR STONY SOILS.

Sources of information: RYAN Field: 10.10.78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1		100	94	75	56	35	24	18			12			6	
2															
3															
4															

L.L. 67 P.I. 43 L.S. 14.5 D.R. 0.48

Special tests: _____

Group Symbol (unified soil classification system): GP-GC

Geological Description: PARTLY DECOMPOSED DOLERITE.

History: CLOSED 1972-73 - WORKED BY BRIGHTON COUNCIL. PARTLY BASE COARSE MATERIAL. BETTER MATERIAL CRUSHED FOR SEALING.

Remarks: DIMENSIONS 50 x 50 x 5 m