

TASMANIAN CONSTRUCTION MATERIALS REGISTER

1143P/M
(BMC Resources)

Serial No. 75/31 Grid Reference EN 196705 Map Sheet No. 8312

Name of Owner/Quarry: DMR - "Old Road Quarry" - Crooked Billet Creek.

Working Pit/Disused Pit/New Locality: Abandoned many yrs.

Past Production: 8,500 m³ Estimated Reserves: _____

Description of site: Quarry on east side of Midlands Highway just north of Crooked Billet creek.

Limits to expansion: Fence line & old road.

Thickness of overburden: 30-50 cm of stony soil

Sources of information: BMAA Field: 3/10/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): -

Geological Description: Tertiary Basalt

History: Old Bluemetal Quarry (DMR)

Remarks: Dimension: 70 x 30 x 4 m

Not sampled - solid rock