

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 33 Grid Reference 109 934 Map Sheet No 76

Name of Owner/Quarry: P.S. Trethewey - "Mt Vernon"

Working Pit/Disused Pit/New Locality: 9 Sample pits

Past Production: nil Estimated Reserves: Large

Description of site: Pits on hill side (moderately steep)  
Northerly aspect

Limits to expansion: none

Thickness of overburden: 10 cm poor soil

Sources of information: RAPM Field: 6/10/75 Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	15.5	11.8	7.6	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1																	
2																	
3																	
4																	

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): \_\_\_\_\_

Geological Description: Medium sized medium gravel

History: \_\_\_\_\_

Remarks: Not sampled