

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 36 Grid Reference: 080817 Map Sheet No. 75

Name of Owner/Quarry: P.N.D. "Cockatoo Gully Rd" (Owner Sydney Cottage - H.L. Jones)

Working Pit/Disused Pit/New Locality: Not used for 6mthst

Past Production: 100x20x3m³ → 6,000m³ Estimated Reserves: None Large

Description of site: West of Cockatoo Gully Road. Not visible from that road since it is on Western slope of a ridge. (Easily seen from Elderslie Road)

Limits to expansion: None apparent

Thickness of overburden: 20+cm good topsoil

Sources of information: WB Field: 21.2.78 Laboratory: Mines Reference No: 782684

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1		100	91		57	39	31	23	18	15		11	8	6	5
2															
3															
4															

12

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Coarse dolerite gravel and clay

History: _____

Remarks: Pit is a very irregular shape. The least coarse pieces only have been taken.
Called "Jones' pit" by Brighton Council
sampled Rm 30/6/78.