

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 56 Grid Reference 168 895 Map Sheet No 75

Name of Owner/Quarry: Crown: D.M.R.

Working Pit/Disused Pit/New Locality: not used for about 1 1/2 years

Past Production: 1800 m<sup>3</sup> Estimated Reserves: very small.

Description of site: At northern end of Kempton township.  
now being backfilled with waste from Kempton Bypass road.

Limits to expansion: Old road, new road

Thickness of overburden: 60 cm. dark brown rocky soil

Sources of information: RAM Field: 6/10/78 Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	15.3	11.76	7.36	4.75	2.97	1.90	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5														
1																		
2																		
3																		
4																		

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): \_\_\_\_\_

Geological Description: Partly decomposed dolerite → gravel.

History: \_\_\_\_\_

Remarks: not work sampling.