

59

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 59 Grid Reference 327859 Map Sheet No 75

Name of Owner/Quarry: "Lynwood"

~~Working Pit/Disused Pit/New Locality:~~ Not worked for about 2-4 yrs

Past Production: 8,500 m³ Estimated Reserves: Large

Description of site: Quarry cutting through top of ridge.
S.W. side of Colebrook road.

Limits to expansion: None

Thickness of overburden: 210 cm poor soil

Sources of information: RAM Field: 10/10/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	15.0	11.8	7.6	4.75	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1		0	102		39.5	64.7	75.3	78.6	81.7	85.1				88.7	92	94.1	95.5
2		0	10		30	25	10	4	3	3				4	3	2	2
3																	
4																	

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Angular slightly weathered dolerite.

History: Present in 1971 Photography

Remarks: Sampled - (bank of)

Dimensions 70 x 35 x 3.5