

65 ✓

TASMANIAN CONSTRUCTION MATERIALS REGISTER

75

Serial No. 65 Grid Reference 153 700 Map Sheet No. 75

Name of Owner/Quarry: R. Rathbone - Mt. Nassau. "Rathbone Quarry"
This part of quarry:

Working Pit/Disused Pit/New Locality: Not worked for several year.

Past Production: ~2000 m³ Estimated Reserves: small.

Description of site: on east side of quarried valley -
old stockpiles and dumps of impure limestone.

Limits to expansion: size of dump.

Thickness of overburden: N/A

Sources of information: RAAM Field: 14/11/78. Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											
1															
2															
3															
4															

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): G.P.

Geological Description: coarse blocky limestone, silts
and clay.

History: Used for fill several years ago - old
stockpiles and dump.

Remarks: _____