

83

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 8368 Grid Reference 341 759 Map Sheet No 75
Name of Owner/Quarry: Richmond Council - Native Corners Road. - Campania

~~Working Pit/Disused Pit/New Locality:~~ Not used several years.

Past Production: ~ 1,500 m³ Estimated Reserves: very small

Description of site: Pit not occupied by refuse disposal area.

Limits to expansion: not applicable

Thickness of overburden: _____

Sources of information: RAAN Field: 10/10/78 Laboratory: _____ Ref. No.: _____

Sizing analysis: _____ Date: _____

mm	76.2	50.8	38.1	25.4	19.0	15.0	10.0	7.5	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1									100	96.2	94.2	92.7		90.7	46.3	8.3	3.6
2									100	86.7	82.7	80.1		76.9	42.8	28	24.5
3																	
4																	

Not in listing

L.L. _____ P.I. _____ L.S. _____ D.R. _____

Special tests: _____

Group Symbol (unified soil classification system): _____

Geological Description: Decomposed Triassic sandstone.

History: small
is some of sand for many years (in part)

Remarks: _____