

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. 75087 Grid Reference <sup>EN</sup> 367789 Map Sheet No 83121

Name of Owner/Quarry BEVEN BROS

Working Pit/Disused Pit/New Locality: new

Past Production: \_\_\_\_\_ Estimated Reserves \_\_\_\_\_

Description of site: \_\_\_\_\_

No Lease? - across ch from 62

Limits to expansion: \_\_\_\_\_

Thickness of overburden: 2m

Sources of information: VMT Field: 1986 Laboratory: \_\_\_\_\_ Ref.No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	19.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
	75.0	53.0	37.5	26.5											

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): \_\_\_\_\_

Geological Description: Gneiss - with one end of pit in flaggy dolomite (close jointed - no gneiss)

History: Mining site by Richmond Council on Blawie Mountain Rd.

Remarks: No great demand: of sealing pegme