

TASMANIAN CONSTRUCTION MATERIALS REGISTER

Serial No. S2 (b) Grid Reference 383 804 Map Sheet No 75  
 Name of Owner/Quarry: Bevan - Brown Mountain Road.

Working Pit/Disused Pit/New Locality: Not worked 8 yrs +  
 Past Production: 1000 m<sup>3</sup> Estimated Reserves: small.

Description of site: Oblong pit now being colonized by young eucalypts. Situated above road (in height). Also several diggings alongside road.

Limits to expansion: Road (one direction)

Thickness of overburden: 15 cm sandy soil and roots.

Sources of information: RAAM Field: 10/10/78 Laboratory: \_\_\_\_\_ Ref. No.: \_\_\_\_\_

Sizing analysis: \_\_\_\_\_ Date: \_\_\_\_\_

mm	76.2	50.8	38.1	25.4	15.0	9.53	4.76	2.36	1.18	0.60	0.425	0.30	0.15	0.075	0.038
1															
2															
3															
4															

L.L. \_\_\_\_\_ P.I. \_\_\_\_\_ L.S. \_\_\_\_\_ D.R. \_\_\_\_\_

Special tests: \_\_\_\_\_

Group Symbol (unified soil classification system): \_\_\_\_\_

Geological Description: Decomposed Triassic sandstone.

History: \_\_\_\_\_

Remarks: Pit dimensions 100 x 20 x .5 (Av).